



- Machine Taps
- Maschinen-Gewindebohrer
- Machinetappen
- Tarauds machine
- Machos de máquina
- Macho de Máquina



E207



- 1.3 1.4
- 1.2 1.5 7.2 7.3

M	P mm	l_1 mm	l_2 mm	d_2 Ø mm	\square a mm	l_3 mm	z		l_4 mm	e-Code
2	0,40	45	4	2,8	2,1	5	3	1.6	9	E207M2
2.5	0,45	50	4	2,8	2,1	5	3	2.05	12,5	E207M2.5
3	0,50	56	9	3,5	2,7	6	3	2.5	18	E207M3
3.5	0,60	56	11	4,0	3,0	6	3	2.9	20	E207M3.5
4	0,70	63	12	4,5	3,4	6	3	3.3	21	E207M4
5	0,80	70	13	6,0	4,9	8	3	4.2	25	E207M5
6	1,00	80	15	6,0	4,9	8	3	5	30	E207M6
7	1,00	80	15	7,0	5,5	8	3	6	30	E207M7
8	1,25	90	18	8,0	6,2	9	3	6.8	35	E207M8
10	1,50	100	20	10,0	8,0	11	3	8.5	39	E207M10