



- Machine Taps
- Maschinen-Gewindebohrer
- Machinetappen
- Tarauds machine
- Machos de máquina
- Macho de Máquina




E545




- 1.1 1.2 1.3 1.4 2.1 2.2 2.3
- 1.5 1.6 4.3 5.1 5.2 6.1 6.3 7.1 7.2 7.3 7.4 8.1

BA	TPI	d ₁ nom mm	l ₁ mm	l ₂ mm	d ₂ Ø mm	□ a mm	l ₃ mm	z	↔	l ₄ mm	e-Code
BA12	0,28	1,30	40	6,0	2,50	2,0	4	2	1.05	6	E545BA12
BA10	0,35	1,70	41	7,0	2,50	2,0	4	2	1.3	7	E545BA10
BA 8	0,43	2,20	44,5	9,5	2,80	2,2	5	3	1.8	9,5	E545BA8
BA 6	0,53	2,80	44,5	9,5	2,80	2,2	5	3	2.3	9,5	E545BA6
BA 4	0,66	3,60	50	16,5	3,55	2,8	5	3	3	16,5	E545BA4
BA 2	0,81	4,70	58	12,0	5,00	4,0	7	3	4	20	E545BA2



E544



- 1.2 1.3 1.4 2.1 2.2 2.3
- 1.5 5.2 7.1 7.2 7.3 7.4

BA	TPI	d ₁ nom mm	l ₁ mm	l ₂ mm	d ₂ Ø mm	□ a mm	l ₃ mm	z	↔	l ₄ mm	e-Code
BA10	0,35	1,70	41	7,0	2,50	2,0	4	2	1.3	7	E544BA10
BA10	0,35	1,70	41	7,0	2,50	2,0	4	2	1.3	7	E544BA10BLUE
BA 8	0,43	2,20	44,5	9,5	2,80	2,2	5	3	1.8	9,5	E544BA8
BA 8	0,43	2,20	44,5	9,5	2,80	2,2	5	3	1.8	9,5	E544BA8BLUE
BA 6	0,53	2,80	44,5	9,5	2,80	2,2	5	3	2.3	9,5	E544BA6
BA 6	0,53	2,80	44,5	9,5	2,80	2,2	5	3	2.3	9,5	E544BA6BLUE
BA 4	0,66	3,60	50	16,5	3,55	2,8	5	3	3	16,5	E544BA4
BA 4	0,66	3,60	50	16,5	3,55	2,8	5	3	3	16,5	E544BA4BLUE
BA 2	0,81	4,70	58	12,0	5,00	4,0	7	3	4	20	E544BA2
BA 2	0,81	4,70	58	12,0	5,00	4,0	7	3	4	20	E544BA2BLUE