



- Machine Taps
- Maschinen-Gewindebohrer
- Machinetappen
- Tarauds machine
- Machos de máquina
- Macho de Máquina



T110



- 1.8
- 1.7

M	P mm	d ₂ ∅ mm	l ₁ mm	l ₂ mm	l ₃ mm	∅ a mm	z		e-Code
3	0,50	3.5	56	10	6	2.70	4	2.6	T110M3
4	0,70	4.5	63	13	6	3.40	5	3.4	T110M4
5	0,80	6	70	16	8	4.90	5	4.3	T110M5
6	1,00	6	80	20	8	4.90	5	5.1	T110M6
8	1,25	8	90	25	9	6.20	5	6.9	T110M8
10	1,50	10	100	30	11	8.00	5	8.7	T110M10
12	1,75	12	110	36	14	9.00	6	10.4	T110M12