



- Machine Taps
- Maschinen-Gewindebohrer
- Machinetappen
- Tarauds machine
- Machos de máquina
- Macho de Máquina



E510



- 1.5 1.6 2.1 2.2 2.3 3.1 3.2 3.3

M	P mm	l_1 mm	l_2 mm	d_2 Ø mm	\square a mm	l_3 mm	z		l_4 mm	e-Code
3	0,50	48	12,5	3,15	2,50	5	2	2.5	12,5	E510M3
3.5	0,60	50	14	3,55	2,80	5	2	2.9	14	E510M3.5
4	0,70	53	14	4,00	3,15	6	2	3.3	14	E510M4
5	0,80	58	11	5,00	4,00	7	2	4.2	22	E510M5
6	1,00	66	13	6,30	5,00	8	3	5	26	E510M6
8	1,25	72	16	8,00	6,30	9	3	6.8	29	E510M8
10	1,50	80	18	10,00	8,00	11	3	8.5	34	E510M10
12	1,75	89	22	9,00	7,10	10	3	10.3		E510M12